

## **Powder Manufacture**

- ▶ Design Metal Alloy for Customer Needs
- ▶ Support Mixed Powder to Meet Specialized Needs
- ▶ Develop New Material with the Different Composition and Application

## Core Manufacture

- ▶ Provide Core with Various Shape(Block, ER etc.) and High Quality
- ► Support Solution for Core and Application (to reduce total power Loss & total cost down)
- ▶ Provide Core with Specialized Properties such as Core loss & DC Bias